


















Figure 1: Patio (not pergola) has been constructed to Southern side of property. Adjoining property is set significantly lower.





Figure 2: view to property on Southern Boundary below pergola



Figure 3: Material use to construct patio



Figure 6: View of patio from adjoining property (South).




Figure 7: material used to construct side of patio

Note: patio has also been constructed on Northern boundary out of same material. Patio has nil setback to fence. Glass house/conservatory has also already been constructed





Figure 4: View of Patio on Southern Side



Figure 5: Front view of property