

Location plan






Site photos

Page 1 of 2

Existing fencing to the southern boundary (Injune Way) and truncation – previously approved






Existing chain mesh fencing to Joondalup Drive frontage – to be removed, and replaced (in part) as per the recommendations in this report.

DURA-FENZ WorkShop Drawings

Style : CENTURION Commercial (Face Welded)



LOT 805 N°10 INTERIOR WAY BOONDAKUP.

MOBA INDUSTRIAL TRAINING ASSOC.

PROPOSAL TO REPLACE 126 METERS OF BOUNDARY FENCE ALONG THE
BOONDAKUP ROAD WITH DUSTPROOF CURTAINING. 2. FENCE IN HEIGHT.

