









Existing retaining wall as viewed from Lot 21.



Existing retaining wall as viewed from Winton Road.





View of retaining wall from Winton Road travelling north.



Retaining wall not visible from Lot 20 or when travelling south along Winton Road.



Photo shows the existing retaining wall is failing.